


KURRI current status

08. 04. 2015 ishi

LINAC repair work still going on
1. replacement of the rf window done



before replacement




damaged window




after replacement

2. Repair slug tuner



slug tuner pulled
out of DTL1





scratch marks



broken rf finger

repair has been done with a brand new rf finger
and polishing the surface of the tuner


3. Put rf on




but vacuum trouble right away

because of damaged o-ring


Remove obsolete magnets and bases




before



after



before



after

made 3 additional probe ports

red:already
white:added

